AMC Control Panel, Manual Handpad range specifications

Control panel/manual handpad Type	AMC3	AMC4	AMC4 Cutter	AMC4 Engraver	Remote Graphics Handpad	MHP1	MHP2	Custom
No. of keys or switches	21	22	22	22	29	13	5	Your choice
No. of pressure sensitive Jog keys	4	4	4	4	4	6	0	Your choice
Additional Custom keys	None	None	None	None	6	None	None	Your choice
E STOP push button	Yes	Yes	Yes	Yes	Yes	Option	Option	Your choice
Pulse wheel for precision positioning	No	No	No	No	Option	Option	Yes	Your choice
Alphanumeric Display	Standard	Option	No	No	No	None	None	Your choice
Graphics Display	No	Option	Standard	Standard	Standard	None	None	Your choice
No. of Status LEDs	None	None	None	None	None	14	2	Your choice
Feed Rate override rotary potentiometer	No	No	No	No	No	Option	No	Your choice
Digital Feed Rate override	Yes	Yes	Yes	Yes	Yes	No	No	Your choice
Analog Output / Spindle Speed key(s)	Yes	Yes	No	Yes	Yes	No	No	Your choice
AMC Output control keys	2	2	None	None	6 Programmable	2	None	Your choice
Start/Resume Job key	Soft Key	Soft Key	Soft Key	Yes	Soft Key	Yes	Yes	Your choice
STOP Job key	Soft Key	Soft Key	Soft Key	Yes	Soft Key	Yes	Yes	Your choice
Abort Job key	Soft Key	Soft Key	Soft Key	Yes	Soft Key	Yes	No	Your choice
Set Home key	Yes	Yes	Yes	Yes	Yes	No	No	Your choice
Go Home Key	Yes	Yes	Yes	Yes	Yes	No	No	Your choice
Tool Setting key and mode	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Your choice
Digitize (Teach) key	Yes	Yes	No	No	Yes	No	No	Your choice
Kerf key	No	No	Yes	No	No	No	No	Your choice
Pierce Delay key	No	No	Yes	No	No	No	No	Your choice
Input and Output Status keys	Yes	Yes	No	No	No	No	No	Your choice
Remote Job Download Key	No	No	Yes	No	No	No	No	Your choice
Single Step key	No	No	No	Yes	No	No	No	Your choice
Dry Run key	No	No	No	Yes	No	No	No	Your choice
Job Validation key	No	No	No	Yes	No	No	No	Your choice
Job Search Key	No	No	No	Yes	No	No	No	Your choice
Axis selection switch	No	No	No	No	No	No	Yes	Your choice
Fast / Slow jog speed switch	No	No	No	No	No	No	Yes	Your choice
Custom Control Panels	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Your choice